

Instructions for Popcorn Machine

1. Use the spoon and scoop provided on the top of the popcorn bin.
Use two spoons of popping oil for two scoops of kernels.
Put popcorn kernels in the kettle first, then pour in the oil.
2. Close Kettle Lid and close the bin doors.
3. Switch ON the Kettle Stirrer and the Kettle Heater.
4. Listen for the oil to sizzle and for the kernels to start popping.
5. Turn ON the Warming Lamp so the popcorn will stay warm.
6. The popcorn should start to pop out of the kettle in about 3-4 minutes.
7. When the popcorn STOPS popping turn the Kettle Heater and the Kettle Stirrer OFF.
8. Use the handle on the Kettle to tip the Kettle to pour out all of the popcorn. You may need to shake the Kettle gently a little to get all of the popcorn out.
9. Leave the Warming Light on to keep the popcorn warm.
10. The Stirrer and Kettle Heater must remain OFF after the popcorn has been poured out of the Kettle.
11. DO NOT USE flavoring oil or liquid butter inside the popcorn bin.
12. Use Flavoring powder and toss or stir to distribute flavoring.
13. Serve popcorn with the metal scoop.
14. Turn OFF the Warming Lamp when popcorn is no longer being served.
15. Clean up after yourself when finished and popcorn is no longer being served and the remaining popcorn is discarded in the trash.